L	Hits	Search Text	DB	Time stamp
Number				
1	161302	base and movable and axis	USPAT; US-PGPUB; EPO; DERWENT	2004/06/02 12:38
2	956	(base and movable and axis) and ((CMM) or (CNC))	USPAT; US-PGPUB; EPO; DERWENT	2004/06/02
3	101	((base and movable and axis) and ((CMM) or (CNC))) and (predetermined adj distance)	USPAT; US-PGPUB; EPO; DERWENT	2004/06/02 12:41
4	32	<pre>(((base and movable and axis) and ((CMM) or (CNC))) and (predetermined adj distance)) and (predetermined adj position)</pre>	USPAT; US-PGPUB; EPO; DERWENT	2004/06/02
5	9	<pre>((((base and movable and axis) and ((CMM) or (CNC))) and (predetermined adj distance)) and (predetermined adj position)) and ((calculate) or (calculating))</pre>	USPAT; US-PGPUB; EPO; DERWENT	2004/06/02
6	6	<pre>(((((base and movable and axis) and ((CMM) or (CNC))) and (predetermined adj distance)) and (predetermined adj position)) and ((calculate) or (calculating))) and error</pre>	USPAT; US-PGPUB; EPO; DERWENT	2004/06/02
7	136	I 1	USPAT; US-PGPUB; EPO; DERWENT	2004/06/02
8	32	or (CNC))) and (predetermined adj position)) and error and ((calculate) or (calculating))	USPAT; US-PGPUB; EPO; DERWENT	2004/06/02
9	21	or (CNC))) and (predetermined adj position)) and error and ((calculate) or (calculating))) and ((calibrate) or (calibration) or (calibrating) or (calibrated))	USPAT; US-PGPUB; EPO; DERWENT	2004/06/02
10	5	<pre>(((((base and movable and axis) and ((CMM) or (CNC))) and (predetermined adj position)) and error and ((calculate) or (calculating))) and ((calibrate) or (calibration) or (calibrating) or (calibrated))) and ((desired adj position) or (actual adj position))</pre>	USPAT; US-PGPUB; EPO; DERWENT	2004/06/02